



CITY OF
PITTSBURGH
PROPERTY CONDITION REPORT



B110 – Firehouse 14
259 McKee Place
Pittsburgh, Pennsylvania 15213

June 2014



Massaro
www.massarocms.com

Table of Contents

1. Executive Summary
 - 1.1. General Description
 - 1.2. General Physical Condition
 - 1.3. Recommendations - Table 1
2. Team, Purpose and Scope
 - 2.1. PCA Team
 - 2.2. PCA Purpose and Scope
 - 2.3. Document Review and Interviews
 - 2.4. Walk-Through Survey
 - 2.5. Opinion of Probable Costs
 - 2.6. Property Condition Report (PCR)
 - 2.7. Additional Scope Considerations
3. Element Descriptions and Observations
 - 3.1. Site
 - 3.2. Substructure
 - 3.3. Shell
 - 3.4. Interiors
 - 3.5. Services
 - 3.6. Equipment & Furnishings
 - 3.7. Special Construction
4. Appendices:
 - 4.1. Property Maps / Drawings
 - 4.2. Accessibility
 - 4.3. Energy Audit

1 Executive Summary

1.1 General Description

The City of Pittsburgh contracted with MCMS to provide a Property Condition Assessment (PCA) in order to prepare a Property Condition Report (PCR) of the subject property, located in the Central Oakland neighborhood at 259 McKee Street, Pittsburgh, PA. A walk-through survey of the subject property was conducted on July 9, 2013.

The subject property consists of a 1-story fire station with basement; containing an apparatus room, storage, break room, lockers and offices. The building was constructed in 1944. The property is on a 0.3 AC municipal lot that includes a former police station that abuts the fire station. The police station is currently leased and occupied by the Oakland Career Center, and is incorporated in this assessment.

1.2 General Physical Condition - POOR

The general physical condition of properties is typically categorized as:

- **New** – Constructed within the last year.
- **Good** – Well constructed and maintained, without significant deficiencies.
- **Fair** – Apparent deferred maintenance issues and deficiencies that can be remedied at reasonable cost.
- **Poor** – Inadequately constructed and/or maintained, with substantial deficiencies that require significant cost and scope of work to remedy. Some items may require additional detailed analysis and testing to fully define the deficiency.
- **Derelict** – State of deficiencies and failure to maintain renders the property unfit for use and may pose direct hazard to occupants and/or the general public. For these properties, either major rehabilitation or demolition and replacement will be required.

Generally, the property appears to have been constructed within typical industry standards for the building type and period of construction. However, based on the findings of this PCA, the subject property is considered to be in **POOR** overall condition. The major deficiencies and deferred maintenance issues are as follows:

- The masonry enclosure is in disrepair and in need of restoration.
- The roofing system is in disrepair and will need replaced within 5 years.
- The masonry parapets will need rebuilt during the proposed roofing replacement.
- The apparatus room slab needs repair and waterproofing.
- The boiler and hot water heater lack provision for combustion air.
- The fire detection/notification and protection systems are inadequate.

1.3 Recommendations – Table 1

See various sections of this Report for details. For the Summary of Recommendations see Table 1, Attached.

Immediate and Short Term Repairs - Table 1
 Opinion of Probable Costs
 Building #B110 - Firehouse 14. OAKLAND
 MCMS Project No. 13-707.05

Section	Item	Quantity	Unit	Unit Cost	Cycle Replacement	Replacement %	Immediate Total	Short-Term Total
3.1	SITE							
a	Clear vegetation, prep and paint guardrails and well grates.	1	EA	\$3,000			\$3,000	
b	Clear and repair trench drains	1	EA	\$2,500			\$2,500	
c	Concrete paving repairs and joint sealant.	1	EA	\$4,000			\$4,000	
d	Remove overgrown vegetation at NW	1	EA	\$0				
e	Replace flagpole	1	EA	\$5,000				\$5,000
3.2	SUBSTRUCTURE							
3.3	SHELL							
a	Seal cracks and waterproof apparatus bay slab	1	EA	\$7,500				\$7,500
b	Masonry restoration, lintel replacement, sealants	1	EA	\$270,000				\$270,000
c	Remove and Replace Roof Deck	4,420	EA	\$66				\$291,720
d	Replace roofing system (5yrs)	4,420	SF	\$28				\$121,550
e	Repair existing roof defect at Firehouse roof	1	EA	\$3,000				\$3,000
3.4	INTERIORS							
a	Provide warning signage and protection at low headroom over Firehouse stair	1	EA	\$150			\$150	
3.5	SERVICES							
	Plumbing							
a	Install backflow preventer	1	EA	\$3,300			\$3,300	
	HVAC							
b	Boiler safety testing	1	EA	\$250			\$250	
c	Calibrate thermostats	1	EA	\$800			\$800	
d	Provide combustion air ductwork per code.	1	EA	\$9,000			\$9,000	
	Fire Protection							
e	Add Fire Alarm devices and fire extinguishers	1	EA	\$1,800				\$1,800
f	GFI receptacles	1	EA	\$1,800				\$1,800
g	Emergency Light/sign fixtures	1	EA	\$2,750				\$2,750
h	CO detector in Boiler Room	1	EA	\$3,500				\$3,500
	Electrical							
3.6	EQUIPMENT AND FURNISHINGS							
3.7	SPECIAL CONSTRUCTION							
TOTALS							\$23,000	\$708,620

2 Team, Purpose and Scope

2.1 PCA Team

Team Lead, Site, Architectural, Accessibility, Drawings:

Massaro CM Services, LLC

120 Delta Drive
Pittsburgh, PA 15238
(412) 963-2800
Alyssa Kuhns
David A. Parker AIA, NCARB

Structural:

A&A Consultants, Inc.

707 East Street
Pittsburgh, PA 15212
(412) 323-2200
Craig Bollinger, PE

Enclosure (Roof and Exterior Walls):

American Micronics, Inc.

P.O. Box 14354
Pittsburgh, Pa 15239
(412) 793-1889
Ron Paul

Mechanical, Electrical, Plumbing, Fire Protection, Energy Audit:

Cosmos Technologies, Inc.

700 River Avenue, Suite 412
Pittsburgh, PA 15212
(412) 793-1889
Mike Yanosko, CEM

2.2 PCA Purpose & Scope

Massaro Construction Management Services (MCMS) is providing Property Condition Assessment (PCA) services in general accordance with the ASTM E2018-08 *Standard Guide for Property Condition Assessments; Baseline Property Condition Assessment*. This standard is widely recognized in the real estate industry as a benchmark tool for evaluating the condition of real property. The City of Pittsburgh is undertaking a multi-year effort to complete PCA's with the following goals:

- Gain greater insight into the current scope and condition of their real property assets.
- Quantify physical deficiencies and immediate repair needs along with short and medium term capital reserve needs for preservation of those assets.
- Identify opportunities to implement Energy Efficiency Measures (ECM) to reduce energy use and hence, energy and/or demand costs.

The general scope of work in a typical PCA includes the following tasks:

- Document Review and Interviews
- Walk-Through Survey
- Opinion of Probable Costs
- Property Condition Report

2.3 Document Review and Interviews

Documents provided by the Owner include: architectural drawings dated 1944 for the Firehouse, as well as architectural drawings dated 2012 for interior alterations to the abutting former police station now leased by Oakland Career Center. Although formal interviews were not performed the Point of Contact (POC) Mr. Henry Cafardi, Facilities Maintenance Supervisor, was available to answer questions.

2.4 Walk-Through Survey

The scope of the walk-through survey was limited to representative visual observations of site and property improvements and should NOT be considered all-inclusive. It is conducted without protective clothing, exploratory probing, removal or relocation of materials, testing, or the use of equipment, such as ladders (except as required for roof access), stools, scaffolding, metering/testing equipment, or devices of any kind. Out-of scope issues include but are not limited to:

- Operating, measurement and/or testing of any building systems.
- Assessment of any process-related equipment or systems.
- Assessing components of systems that are not readily observable.
- Entering limited access or confined spaces.
- Accessing pitched roof areas or any roof area that appears unsafe.
- Determining applicability of Life Safety/Fire Protection code requirements.

2.5 Opinion of Probable Costs

Replacement, repairs, and routine maintenance of various building components and systems are discussed in various sections of this report and opinions of their probable costs are summarized for the evaluation period in the attached tables. Per ASTM E2018-08; costs indicated should be considered preliminary, order of magnitude budgets. Actual costs most probably will vary from those contained within depending on such matters as type and design of suggested remedy, quality of materials and installation, manufacturer and type of equipment or system selected, field conditions, whether a physical deficiency is repaired in part or replaced in whole, phasing of the work (if applicable), quality of contractor, quality of project management exercised, market conditions, and whether competitive pricing is solicited, etc. Certain opinions of probable costs can not be developed within the scope of this assessment without further study. Where applicable, the opinion of the probable costs for further study will be included.

- **Immediate Costs** are to remedy those deficiencies that require immediate action as the result of any of the following:
 - material existing or potential unsafe condition
 - material building or fire code violations
 - conditions that if left uncorrected have the potential to result in or contribute to critical element or system failure within one year or will result most probably in a significant escalation of its remedial cost.
- **Short-Term Costs** are to remedy physical deficiencies, such as deferred maintenance, that may not warrant immediate attention, but require repairs or replacements that should be undertaken on a priority basis in addition to routine preventative maintenance. Unless noted otherwise, generally the time frame for such repairs is 1-2 years. Such opinions of probable costs may include costs for testing, exploratory probing, and further analysis; or these services may be evaluated separately.

2.6 Property Condition Report (PCR)

The Property Condition Report documents the findings of the PCA. This report is for the use of this Client only, for the stated purpose above. Specific language in the descriptions of the various PCA processes, intent, scopes of work, and/or definitions throughout Section 1-2 of this PCR are excerpted directly in whole or in part from the ASTM E2018-08 Standard (herein the 'Standard') document without specific attribution. All rights remain with the ASTM. In the event of any discrepancy between statements in this Report and the Standard, the scope and intent in the respective sections of the Standard shall govern. A complete copy of the Standard may be made available upon request.

2.7 Additional Scope Considerations

For this assessment, in addition to the baseline PCA tasks, further considerations are taken into account and additional deliverables are included as follows:

- **Schematic Floor Plans** – Produced using Autodesk Revit™ Building Information Modeling (BIM) software, and including limited field check of representative dimensions and documentation of changes to layout. These drawings and associated floor area information provide a helpful quick reference tool for General Services and Architectural Division staff. They are schematic in nature and should NOT be considered complete documentation of as-built conditions. City develop a BIM Standard and/or Computer Aided Facilities Management (CAFM) program in the future, this initial modeling effort can be further enriched and aligned with those initiatives.
- **Energy Audit** – Level 1, Walk-Through Analysis, per the *Procedures for Commercial Building Energy Audits, 2nd Ed.* Published by the American Society of Heating, Refrigeration and Air Conditioning Engineers (ASHRAE). This Audit provides an overview of building systems and their functional operation, benchmarks the Energy Use Index (EUI) of the subject property against comparables, identifies low/no-cost changes to current Operations and Maintenance (O&M) process to provide savings, and identifies potential capital improvements for further study.

3 Element Descriptions and Observations

3.1 Site

The building is located on an approximately one-third acre (0.3AC) parcel containing both the Firehouse and an adjoining (but not internally connected) former police station. Overall the Site is in Fair condition.

1. Topography and Drainage – The site is relatively flat, rising slightly from McKee Place along Louisa St. The site appears to be positively drained away from the building. Trench drains along McKee and Louisa appear to be full of sediment. Window well railings and gratings need painted

Recommendation – Clean and repair trench drains. Prep and paint railings and well gratings.

2. Access and Egress – Vehicle access to the subject property is available from McKee Pl. Egress from the building to grade is available from the first level only.
3. Paving, Curbing and Parking – The site paving and adjacent sidewalks are concrete and generally in Poor condition. Concrete apron has areas of joint spalling and vegetation growing in joints, the apron is spalled at the bollards due to a lack of expansion joint material. Cracks, differential settlement and joint dislocations are evident throughout. Five (5) informal (unlined) parking spaces are accessible from McKee Pl. and available for FD. Accessible parking is NOT available. Concrete apron has areas of joint spalling and vegetation growing in joints, the apron is spalled at the bollards due to a lack of expansion joint material.

Recommendation: Repair / Replace broken and settled concrete paving and walks. Seal all joints.

4. Landscaping and Appurtenances – Landscaping and plantings consist primarily of grass lawns and several planting beds. Unimproved vegetation and invasive trees overgrown along the NW side of the building limit access for maintenance.

Recommendation: Cut back overgrown vegetation.

5. Site Amenities / Accessory Structures- A low-rise segmental retaining wall in Good condition runs along the west side of the drive. The flagpole on site is heavily rusted and in need of replacement.

Recommendation: Replace the flagpole.

3.1 Site: Photos



ST1 – Overgrown vegetation along NW side



ST2 – View from McKee Place, flagpole in foreground



ST3 – Looking NE along Louisa St.



ST4 – Former Police Station, now Oakland Career Center, looking NW along Semple St.



ST5 – Trench drain filled with sediment



ST6 – Concrete pavement – differential settlement, open joints

3.2 Substructure

This visual inspection included the observation of the substructure including foundation and basement construction. Overall the Substructure is in Good condition.

1. Foundation
 - a. Constructed of masonry - Good condition: the basement walls have a few light cracks.
 - b. NW wall has window wells constructed of concrete; they contain debris but are in Good condition.
2. Slab on grade: The basement floor is concrete and has some light cracks.

3.3 Shell

1. Overall the Shell is in POOR condition.
2. Building Frame & Floors
 - 2.1. The first floor of the entire building is constructed of reinforced concrete T-Beams with a center structural wall running west to east.
 - 2.2. The concrete reinforced concrete T Beams are in good condition they have areas of light cracks, light spalls, and exposed rebar that are in good condition.
 - 2.3. The first floor decking of the fire station garage bay has had a topping slab applied. The topping slab has 1/16" to 3/8" longitudinal and transverse cracks. There is also light map cracking at the expansion joint along the center of the bays
 - 2.4. The first floor decking of the rental space is in good condition; a few light cracks and spalls exist but have been painted over.
 - 2.5. The fire station bays have a 4'x4' hole in roof that has been sealed over
 - 2.6. The concrete encased steel roof beams have patches on the encasement, no steel is visible
 - 2.7. The concrete roof decking has patches, but otherwise is good condition

Recommendation - Fire Station Apparatus Room slab cracks should be sealed with epoxy injection and floor waterproofed with sealer to prevent deterioration to floor slab and RCT Beams

3. Building Façade
 - 3.1 Construction: The building walls are constructed with brick masonry. Wall penetrations include: 5 metal man doors, 2 garage doors, 29 windows, 16 glass block windows and 4 ground level skylights on the east end. All doors and windows have metal frames.
 - 3.2 There are areas on west wall and the western half of the north and south walls with light brick cracking, step cracking, brick bulging at lintels and areas of minimal brick displacement
 - 3.3 The joint on the south wall between the police station and firehouse is open 3/8" full height with the cap stone displaced 1/4"
 - 3.4 Parapets are in poor condition with brick cracking and cap stone misalignment
 - 3.4.1 Exterior metal man doors are in good condition. There is light spall in the door trim at the rental area on the south east wall
 - 3.4.2 Window lintels have light/ heavy rust with areas of bulging brick, loss of mortar and minimal brick displacement.

Recommendations

- Parapets need to be programmed for replacement, align with roof replacement.
- Masonry restoration including replacing lintels and sealing open joints

4. Roof Deck
 - 4.1. Construction: Metal edged gyp plank roof decking is installed on the roofs above Fire House 14 (west end older building). The roof deck on the newer east end was not visible. There is no apparent slope to the drains.
 - 4.2. Condition: No conditions were observed that would indicate deck problems. The metal edges on the gyp planks are rusted.
5. Roof Insulation
 - 5.1. Construction: No core cuts were taken.

5.2. Condition: The insulation is assumed to be in fair condition.

6. Roof Membrane

6.1. The roof system on the Oakland Career Center is constructed with a white TPO single ply membrane. The roof system on Firehouse 14 is constructed of a Modified Bitumen membrane with a black granule surface.

6.2. Condition: The roof membrane on the Oakland Career Center appeared in fair condition. The roof system on Firehouse 14 appeared in poor condition. The modified bitumen system on the Firehouse contains numerous ridges and blisters.

7. Membrane flashings

7.1. Construction: The perimeter and curb flashings are constructed with the same membranes as used on the roofs.

7.2. Condition: The membrane flashing systems on the Oakland Career Center are in fair condition. The membrane flashing systems on the Firehouse are in poor condition. The flashing is loose from the wall and buckled (wrinkles) in some areas with numerous open vertical joints. The flashing extends up and over top the metal coping. Numerous repairs were observed. Repairs were made using roof cement only and have failed and are open.

8. Perimeter Terminations

8.1. Construction: The building walls extend above the roof line creating a parapet on the exterior walls of both roof areas. The parapet walls on the Firehouse are terminated with metal coping that has been covered by membrane flashing. The parapet walls on the Oakland Career Center are terminated with metal coping that was installed overtop of existing limestone coping. The interior higher wall flashing is terminated with metal bar on the Firehouse and with metal counter flashing on the Career Center.

8.2. Condition: I could not observe the metal coping except for the exterior face on the Firehouse. The metal coping appears in fair condition. The mortar bed joint on the original limestone coping is deteriorating.

9. Roof Top Penetrations

9.1. Firehouse 14: 6 vent pipes and two surface mounted condensers. Career Center: 5 vent pipes, 6 pitch pockets, and 2 HVAC units.

9.2. Condition: The penetrations are in fair condition.

10. Drainage System

10.1. Construction: The high bay roof on Firehouse 14 drains into 4 through wall scuppers and into conductor heads with downspouts onto the roofs below. The balance of the roof drains into interior roof drains (Firehouse 14 – 4 drains, Career Center – 5 drains). There is no apparent slope to the drains.

10.2. Condition: Firehouse 14: The north side low roof area is covered with ponded water, water ponds at all drains, 1 drain on the south side and both drains on the north side appear clogged. Career Center: There is some minor ponding but the drains appear to be operating properly.

11. Access

11.1. Providing an extension ladder is the only access to the roofs.

CONCLUSIONS

Occasional leaks are reported in the Firehouse and none in the Career Center.

The building walls are in fair condition. A few defects were observed. Some cracked bricks and missing mortar were observed. The caulking/sealant at the doors and windows is in poor condition.

The roof decking appears to be in fair condition on the Firehouse and in good condition on the Career Center. We did not observe any signs that would suggest a serious problem with the decking systems at this time.

The roof membrane and flashing systems are in poor condition on the Firehouse and in fair condition on the Career Center. The open, loose and buckled flashing on the Firehouse areas should be monitored and repaired until the roof is replaced.

The metal coping is covered with roof membrane and should be monitored and repaired until the roof is replaced.

The roof top units and penetrations are in fair condition.

The drainage system is in fair condition. The clogged drains on the Firehouse should be cleaned. The debris should be cleaned from the roof surface and continue to be cleaned twice yearly.

With proper Maintenance and corrective repairs, it is our opinion that the Firehouse roofing system is in a maintainable condition for the next five years and the Career Center roofing system is in a maintainable condition for the next ten years.

Estimates

1 year: Repair existing roof defects - Estimated cost: \$3,000. Replace caulking and sealant at doors and windows – this work does not have to be done at one time but as the maintenance budget permits. Inspect roofs and walls yearly and remove debris – Estimated cost: None (perform with in-house personnel)

5 year: Replace Firehouse 14 roofing and flashing system – Estimated cost: \$79,560 (4,420 SF x \$18/SF)

10 year: Maintain a pro-active maintenance program. Inspect the roof system and walls on a regular schedule – minimum twice a year (late spring and late fall). Estimated cost: none (perform in-house)

3.3 – Shell: Photos



SH1 – NW wall +/- 2' from corner – light vertical crack full height



SH2 – Center pier at apparatus doors; bulging brick above lintels



SH3 – SW wall - Step cracking from window lintel, Light Vertical crack from lintel to coping, rusted lintel



SH4 – SE corner @ upper level – step cracking from lintel



SH5 – SE corner @ upper level – missing sealant



SH6 – NE wall above Career Center – missing sealant

3.3 – Shell: Photos Continued



SH7 – View from above – Firehouse 14 at left, Career Center (white roof) at right



SH8 – SE lower roof looking SW




SH9 – SE lower roof looking NE – ponding water



SH10 – Upper roof looking NE – ponding water



SH11 – Upper roof; ponding water, open and loose flashing



SH12 – NW lower roof looking NW – ponding water all drains clogged

3.3 – Shell: Photos Continued – Career Center roof



SH13 – Upper roof looking S



SH14 – Lower roof looking S



SH15 – View from upper roof looking NE



SH16 – View from upper roof looking NE



SH17 – Lower roof looking SW



SH18 – Lower roof – debris at roof drain

3.4 Interiors

Firehouse 14

1. Interior Construction - Interior partitions are primarily brick and/or glazed tile masonry construction. Doors and frames are typically wood construction with commercial grade hardware. Overall the Interiors are in Fair condition.
2. Stairs – The concrete stairs are in Good condition. However, the Firehouse stair has dangerously low headroom and does not comply with current code.

Recommendation – Provide warning signage and protection at low structure above stair.

3. Interior Finishes – Much of flooring in the building is simply exposed concrete. The office/kitchen/dormitory areas have resilient tile flooring in Fair condition. The restroom/locker room flooring is ceramic tile. Ceilings are typically cement plaster throughout and are in Good condition.

Oakland Career Center

1. Renovations to the Career Center were completed in 2012. The interior construction and finishes in the Career Center are in New or Good condition.

3.4 Interiors: Photos



11 – Apparatus bay



12 – Dormitory



13 – Locker area



14 – Office



15 – Lower level – fitness center




16 – Lower level – storage / work room

3.4 Interiors: Photos Continued – Career Center



17 – Entry corridor




18 – Interior offices



19 – Office



110 – Corridor to offices / interior stair down



111 – Multipurpose Room



112 – Lower level - training center

3.5 Services - Plumbing

Building Plumbing Systems

1. Fixtures

- 1.1. General Description: The plumbing system is served by a combination of sanitary fixtures, supply and drain piping, and supply water meter service. Serving the locker room, men's and ladies' rooms, lunch room kitchen area, and laundry.
- 1.2. Construction
 - 1.2.1. Four (4) toilets
 - 1.2.2. Six (6) lavatory sinks
 - 1.2.3. One (1) urinal
 - 1.2.4. Four (4) shower heads
 - 1.2.5. One (1) kitchen type sinks
 - 1.2.6. One (1) janitor's sink
 - 1.2.7. One (1) wash machine (laundry)
 - 1.2.8. One (1) laundry sink
- 1.3. Condition Assessment
 - 1.3.1. Condition: **Fair**

2. Domestic Water Production

- 2.1 Construction: The domestic water heating system is served by one A.O. Smith (1) 50 gallon, commercial water heater and supply piping.

3. Utilities

- 3.1 General Description: Potable water supply
- 3.2 Construction
 - 3.2.1 Original meter, shut-off valve, and piping.
 - 3.2.2 No back-flow prevention.
- 3.3 Condition Assessment: **Fair**

4. Conclusion:

- 4.1 The plumbing systems are in fair to poor overall condition. Routine maintenance should continue to extend serviceability.

5. Estimates: Suggested remedies and Opinion of probable cost

- 5.1 De minimus conditions
 - 5.1.1 Insulate supply pipes from water heaters.
- 5.2 Immediate Costs
 - 5.2.1 Install back-flow preventer: \$2,000.


3.5 Services Photos - Plumbing



P1 – Lavatory sinks - Typical



P2 – Locker area showers - Typical



P3 – Urinal - Typical



P4 – Service sink



P5 – Water meter, pressure reducer and shut-off valve



P6 – Domestic water heater

HVAC

1. HVAC System – General Description: Primary space heating for fire station is supplied by a central hot water system. It is comprised of central equipment, distribution systems, and room level terminal units. The boiler, piping, and room terminal units are reported to be original to the building.

1.1. Room level terminal units: Room based heating terminals are comprised of various combinations of local window air conditioners, hot water convectors, and exhaust fans. Individual room heating units are interconnected with hot water supply and return distribution piping.

Condition: Room terminal units - **Poor**

1.1.1. Physical Deficiencies:	No RAD Control Valves	
1.1.2. Functional Deficiencies:	None reported or observed	
1.1.3. Performance Deficiencies:	None reported or observed	
1.1.4. Maintenance observations:	WACU casing corrosion	
1.1.5. Remaining useful life observations (RUL)	WACU:	1-3 years
	Heating, Cooling, Ventilation:	5+ years
	DCVEX:	10+ years

1.2. Heating Distribution System: The hot water heating distribution system includes black steel hot water supply and return piping and one (1) in-line centrifugal hot water pump.

Construction:

Hot water piping: Black steel
Piping Insulation: None Observed
One (1) Pump: Fractional HP, in-line centrifugal
Pump controls: Partially de-commissioned

Condition: Heating distribution system - **Poor**

Physical Deficiencies:	No piping insulation	
Functional Deficiencies:	None reported or observed	
Performance Deficiencies:	None reported or observed	
Maintenance observations:	None reported or observed	
Remaining useful life observations (RUL)	Pumps:	3-5 years

1.3. Central Boiler System:

Construction: The hot water system consists of one (1) Crane 630 MBH boiler, one (1) circulation pump, black steel circulation piping, expansion tank, black steel fuel piping, boiler mounted safety devices, and vent pipe, and temperature controls. The boiler is fuelled by natural gas and is natural combustion type. The boiler, circulating pump, control system are functioning beyond their expected useful life (EUL), and are located in the basement mechanical equipment room (MER). The boiler inspection certificate is displayed but out-of-date. The hot water heating control system consists of original, partially decommissioned field mounted devices.

Condition: Central Boiler - **Poor**

Safety Concerns:	Boiler permit, Boiler safety controls testing
Code non-compliance issues:	No Dedicated combustion air system
Physical Deficiencies:	None reported or observed
Functional Deficiencies:	Simultaneous heating and cooling
Performance Deficiencies:	OA reset
Maintenance observations:	Boiler general condition
Remaining useful life observations (RUL):	1-3 years

1.4. Controls

Construction: The central and room level control systems are reported to be original to the building. The controls are observed to be in a partially de-commissioned state. The boiler and hot water pump controls appear to employ outside air temperature input.

Condition: Controls - **Poor**

1.5. Performance Observations: Energy and Sustainability: The heating system is consuming excess natural gas due to lack of fully functioning controls for the hot water heating system, old low efficiency boiler, uncalibrated thermostats, lack of local control from se-lf-contained radiator thermostatic valves, and lack of set-back controllers.

1.6. Utilities

General Description: Natural gas.

Construction: Low pressure natural gas meter and associated threaded, black steel piping.

Condition Assessment: **Fair**

1.7. Conclusion: The HVAC system as a whole is in **Poor** condition.

1.8. Estimates: Suggested remedies and Opinions of Probable Cost

De minimus conditions

Boiler Safety Testing: \$250 (Fire and Ice heating)

Immediate Costs

Calibrate Thermostats: \$800

Combustion air for boiler and water heater: \$7,500

Short-Term Costs

MER Insulation (Armaflex type): \$2,000

3.5 Services Photos – HVAC



H 1 – HW Radiator – Apparatus Room - Typical




H 2 – Direct Connect Vehicle Exhaust System (DCVEX)



H 3 – Dormitory WACU - Typical



H 4 – HW Radiator Dormitory - Typical



H 5 – HW Heating Boiler



H 6 – Lower level WACU and HW Radiator

3.5 Services - Fire Protection

Building Fire Protection and Life Safety Systems

1. Flammable Gas Storage
 - 1.1. Liquid Propane (LP) gas tank is stored in the apparatus room/Vehicle garage with commercial BBQ grill. **Code Violation.**
2. Fire Extinguishers
 - 2.1. No observable fire extinguishers present. **Potential Code Violation.**
3. Alarm Systems
 - 3.1. No observable fire or smoke alarm system present. **Potential Code Violation.**
 - 3.2. No observable fire or smoke detectors present. **Potential Code Violation.**
 - 3.3. No observable fire pull-stations present.
4. Smoke Evacuation System and Stairwell Pressurization
 - 4.1. No Smoke Evacuation System or Stairwell Pressurization.
5. Sprinklers and Standpipes
 - 5.1. No sprinkler system present.
6. Emergency Lighting
 - 6.1. No observable emergency lighting present. **Potential Code Violation.**
7. Ground Fault Interruption
 - 7.1. GFI's not present in all kitchen and laundry connections. **Potential Code Violation.**
8. Conclusions:
 - 8.1. The building fire protection and life safety systems are physically deficient. **Multiple potential code violations due to lack of devices and systems.**
9. Estimates: Suggested remedies and Opinions of probable cost
 - 9.1. De minimus conditions
 - 9.1.1. Remove liquid propane (LP) gas tank for BBQ grill.
 - 9.2. Short-Term Costs
 - 9.2.1. Add a minimum of six (6) fire extinguishers
 - 9.2.1.1. Men's dormitory: \$250
 - 9.2.1.2. Locker room: \$250
 - 9.2.1.3. Apparatus room: \$250
 - 9.2.1.4. Lunch room: \$250
 - 9.2.1.5. Basement landing: \$250
 - 9.2.1.6. Outside boiler room: \$250
 - 9.2.2. Add a minimum of six (6) smoke-fire detector/alarms:
 - 9.2.2.1. Men's dormitory: \$350
 - 9.2.2.2. Locker room: \$350
 - 9.2.2.3. Lunch room: \$350
 - 9.2.2.4. Basement landing: \$350
 - 9.2.2.5. Outside boiler room: \$350
 - 9.2.3. Add a minimum of three (3) GFI receptacles – LED type: \$1,800
 - 9.2.4. Add a minimum of five (5) emergency light/sign fixtures – LED type: \$1,800
 - 9.2.5. Add Carbon Monoxide Detector-Alarm in Boiler Room: \$3,500

3.5 Services - Electrical

Building Electrical Systems

1. Interior Lighting

1.1. General Description: interior lighting is provided to the building by a combination of windows, and recessed mount and surface mount florescent fixtures.

1.2. Construction

Room	Lighting Fixtures				Lamps				Comments
	Q1	Mount	Length	Type	W1	Q2	Type	W2	
Toilet & Shower	4	Recess	4'	Fluor.	40	2	T12	256	Man Sw, Mag Bal, 8'AFF
Apparatus Room (a)	10	Suspend	4'	Fluor.	40	2	T12	-	Man Sw, Mag Bal
Apparatus Room (b)	3	Suspend	8'	Fluor.	80	1	T12	-	Man Sw, Mag Bal
Apparatus Room (c)	1	Surface	4'	CFL	40	4	T12	960	Man Sw
Stairwell (a)	1	Surface	2'	Fluor.	32	1	T12	-	Circular Lamp
Stairwell (b)	1	Surface	4'	Fluor.	40	2	T12	90	Man Sw, Mag Bal, 8'AFF
Lunchroom (a)	1	Recess	4'	Fluor.	32	4	T8	-	Man Sw, Mag Bal, 8'AFF
Lunchroom (b)	1	Recess	4'	Fluor.	40	4	T12	230	Man Sw, Mag Bal, 8'AFF
Chiefs Office (a)	2	Recess	4'	Fluor.	40	2	T12	-	Man Sw, Mag Bal, 8'AFF
Chiefs Office (b)	2	Recess	4'	Fluor.	40	1	T12	192	Man Sw, Mag Bal, 8'AFF
Captains Office (a)	1	Recess	2'	Fluor.	32	2	T8	-	Man Sw, Mag Bal, 8'AFF
Captains Office (b)	2	Recess	4'	Fluor.	40	4	T12	-	Man Sw, Mag Bal, 8'AFF
Captains Office (c)	1	Surface	na	Incand.	75	1	na	367	Man Sw, Mag Bal, 8'AFF
Lounge (a)	2	Recess	2'	Fluor.	40	2	T12	-	Man Sw, Mag Bal, 8'AFF
Lounge (b)	2	Recess	4'	Fluor.	40	4	T12	-	Man Sw, Mag Bal, 8'AFF
Lounge (c)	2	Recess	4'	Fluor.	40	1	T12	448	Man Sw, Mag Bal, 8'AFF
Entrance	1	Surface	na	Task	75	1	na	75	Man Sw
Dormitory	3	Surface	2'	Fluor.	40	2	T12	192	Man Sw, Mag Bal, 8'AFF
Locker Room	1	Surface	2'	Fluor.	40	2	T12	64	Man Sw, Mag Bal, 8'AFF
Weight Room (a)	2	Suspend	4'	Fluor.	40	2	T12	-	Man Sw, Mag Bal, 8'AFF
Weight Room (b)	4	Suspend	8'	Fluor.	80	2	T12	640	Man Sw, Mag Bal, 8'AFF
Storage	1	Surface	na	Incand.	75	1	na	75	Man Sw
Boiler Room (a)	2	Suspend	2'	Fluor.	32	1	T8	-	Circular Lamp
Boiler Room (b)	1	Suspend	8'	Fluor.	80	2	T12	-	Man Sw, Mag Bal
Boiler Room (c)	1	Surface	na	Incand.	75	1	na	239	Man Sw
Coal Storage	1	Surface	na	Incand.	75	1	na	75	Man Sw
Laundry - Work Room (a)	3	Surface	4'	Fluor.	40	4	T12	-	Man Sw, Mag Bal
Laundry - Work Room (b)	2	Surface	4'	Fluor.	40	2	T12	-	Man Sw, Mag Bal
Laundry - Work Room (c)	1	Suspend	8'	Fluor.	80	2	T12	640	Man Sw, Mag Bal

Note #1: Two (2) total lamps out

AFF = Mounting Height Above Finished Floor

Flour = Fluorescent

Length = Standard Fixture Length

Mag Bal = Magnetic Ballast

Man Sw = Manual Wall Switch

Q1 = Fixture Quantity

Q2 = Lamp Quantity per Fixture

W1 = Watts per Lamp

W2 = Watts/room (Net: 0.80 BF applied)

- 1.3. Condition Assessment: Interior
 - 1.3.1. Condition: Fair

2. Power Distribution
 - 2.1. Construction and condition
 - 2.1.1. Distribution panels (original to building): Condition-**Fair**
 - 2.1.2. General Receptacles (original to building): Condition-**Fair**

3. Utilities Service
 - 3.1. Construction
 - 3.1.1. One (1) 3-phase original electric service.
 - 3.2. Condition Assessment
 - 3.2.1. Condition Power Service: **Fair**
 - 3.2.2. Condition Electric Meter: **Good**

4. Conclusions:
 - 4.1. The interior electrical system as a whole is in Fair condition.

5. Estimates: Suggested remedies and Opinion of probable cost
 - 5.1. Immediate Costs
 - 5.1.1. See GFI in Life Safety section.
 - 5.1.2. Add occupancy sensors for dormitories and work areas: \$1,700

3.5 Services Photos – Electrical



E 1 – Lighting – Apparatus Room



E 2 – Lighting - Lounge



E 3 – Lighting Lower level work room



E 4 – Power service entrance



E 5 – Meter



E 6 – Main power panel

Building Mechanical Systems: HVAC 4.5.1

1. HVAC System – General Description: Primary space HVAC for Career Center is supplied by a central hot water heating system, Roof-top HVAC packed units (RTU), and Split-system Air Handlers (AHU). It is comprised of central equipment, zone level equipment, distribution systems, room level terminal units, and Direct Digital Controls (DDC). The boiler, piping, RTU's, AHU's with split-system air cooled condensing units (ACCU), and DDC controls are new. Room terminal units are a combination of pre-existing and new.
 - 1.1. Room level terminal units: Room based heating terminals are comprised of various combinations of hot water convectors, supply diffusers, return air grills, exhaust grills, and exhaust fans. Individual room heating convectors are interconnected with hot water supply and return distribution piping. Individual air terminals are interconnected with supply air ducts and return air plenums.
 - 1.1.1. Construction Room terminal units - Heating Convectors: *Existing* baseboard and radiators without zone control valves.
 - 1.1.2. Condition: Room terminal units - Heating Convectors: **Good**
 - 1.1.3. Construction Room terminal units – Air Terminals -1: *Existing* round supply air diffusers.
 - 1.1.4. Condition: Room terminal units - Air Terminals -1: **Good**
 - 1.1.5. Construction Room terminal units – Air Terminals -2: *New* supply air diffusers and return air grills.
 - 1.1.6. Condition: Room terminal units - Air Terminals -1: **New**
 - 1.2. Hot Water Heating Distribution System:
 - 1.2.1. Construction: The hot water heating distribution system includes black steel hot water supply and return piping and two (2) in-line centrifugal hot water pumps.
 - 1.2.2. Condition: **New**
 - 1.3. Central Boiler System:
 - 1.3.1. Construction: The hot water system consists of one (1) Buderus high-efficiency boiler, two (2) circulation pumps, copper circulation piping, expansion tank, black steel fuel piping, boiler mounted safety devices, dedicated combustion air and direct vent piping, and temperature controls. The boiler is fueled by natural gas and is sealed combustion type. The boiler, circulating pump, control system are new and are located in the basement mechanical equipment room (MER).

<u>Location</u>	<u>Boiler</u>	<u>Type</u>	<u>Fuel</u>	<u>Comb</u>	<u>Pumps</u>	<u>Type</u>	<u>XTank</u>	<u>CA</u>	<u>Control</u>	<u>Comments</u>
Basement M.E.R.	1	HW	NG	FD	2	ILC	1	Yes	DDC	New

Note 1: Boiler safety devices and control testing not included in project scope.

Note 2: Boiler safety devices testing should be performed by competent technician, twice during heating season.

CA = Combustion Air supply duct
Comb = Combustion Type
Decom. = De-Commissioned, Partial
HW = Hot Water
ILC = In-Line Centrifugal Pump
M.E.R. = Mechanical Equipment Room
FD = Forced Draft
NG = Natural Gas
XTank = Thermal Expansion Tank

1.3.2. Condition: **New**

Note: The field audit and PCA did not include functional testing of boiler safety devices, water heater safety devices, nor fire or smoke alarm systems.

1.4. HVAC Distribution System:

1.4.1. Construction: The HVAC distribution system includes galvanized ductwork, supply trunks, and return air plenums.

1.4.2. Condition: **New**

1.5. Zoned HVAC System:

1.5.1. Construction: The HVAC system consists of Two (2) roof mounted Trane RTU's and Two (2) Trane AHU's with remote condensing units (ACCU). The units are constant air volume type (CAV).

1.5.2. Condition: **New**

1.6. Controls

1.6.1. Construction: The building control systems are new. The controls system consist of a TACO central hot water heating system controller, Honeywell wireless zone controller, Buderus boiler controller (packaged), room thermostats, and unit mounted Trane Roof-top-unit controls and economizers.

1.6.2. Condition: Controls - **New**

1.7. Performance Observations

1.7.1. Indoor Air Quality (IAQ): The basement Computer room/Class room-B07 has a small connection (4" x 6") to the HVAC supply air system. Fresh ventilation air supply into this room is negligible. This area may be experiencing poor Indoor Air Quality due to lack of fresh air/ventilation, high student loading, and computer heat generation.

1.7.2. Energy and Sustainability: High efficiency HVAC systems and controls resulting in minimum energy costs.

2. Utilities

2.1. General Description: Natural gas.

2.2. Construction

2.2.1. Low pressure natural gas meter and associated threaded, black steel piping.

2.3. Condition Assessment: **New**

3. Conclusion:

3.1. The HVAC system as a whole is new and/or in good condition.

4. Estimates: Suggested remedies and opinions of probable Cost

4.1. De minimus conditions

4.1.1. Add safety covers for open relay contacts associated with TACO controller.

4.2. Short-Term Costs

4.2.1. Add thermostatic radiator and baseboard control valves \$2,200

4.2.2. Add portable HEPA filter unit for room B07: \$800

4.5.1.3 – HVAC: Roof



HVAC 1 – Packaged Roof-Top-Unit (RTU) -1



HVAC 2 – Air Cooled Condensing Unit (ACCU) - 1



HVAC 3 – Exhaust Louver



HVAC 4 – Air Cooled Condensing Unit (ACCU) - 2



HVAC 5 – Packaged Roof-Top-Unit (RTU) -2


4.5.1.4 – HVAC: 1st Floor



HVAC 6 – Office supply air diffuser (typical pre-existing)



HVAC 7 – Hot water heating radiator (typical)



HVAC 8 – Hot water heating baseboard (typical)



HVAC 9 – Community room supply air diffuser & return grills (new)



HVAC 10 – Center offices thermostat



HVAC 11 – Center offices air diffuser (new)

4.5.1.5 – HVAC: Basement



HVAC 12 – Supply duct manifold



HVAC 13 – Hot water heating radiator: Office



HVAC 14 – Hot water heating radiator



HVAC 15 – Office supply air diffuser



HVAC 16 – Storage room piping



HVAC 17 – Computer lab (limited supply air) B07

4.5.1.6 – HVAC: Central Air Handler, Boiler, HW System



HVAC 18 – Air Handling Unit (AHU)



HVAC 19 – Hot water heating boiler - 1



HVAC 20 – Hot water heating boiler - 2



HVAC 21 – Hot water heating boiler (leaking zone manifold)



HVAC 22 – Hot water heating pumping and piping manifold



HVAC 23 – Digital control systems

Building Electrical Systems 4.5.2

1. Interior Lighting
 - 1.1. General Description: interior lighting is provided to the building by a combination of windows, and recessed mount and surface mount florescent fixtures.
 - 1.2. Construction: Efficient T8 lamps and magnetic ballasts.
 - 1.3. Condition Assessment: **New**


2. Power Distribution
 - 2.1. Construction and condition
 - 2.1.1. Distribution panels: Condition-**New**
 - 2.1.2. General Receptacles: Condition-**New**

3. Utilities Service
 - 3.1. Construction
 - 3.1.1. One (1) new electric service.
 - 3.2. Condition Assessment
 - 3.2.1. Condition Power Service: **New**
 - 3.2.2. Condition Electric Meter: **New**

4. Conclusions:
 - 4.1. The interior electrical system as a whole is in fair condition.

5. Estimates: Suggested remedies and Opinion of probable cost
 - 5.1. Immediate Costs
 - 5.1.1. See GFI in Life Safety section.
 - 5.1.2. Add occupancy sensors for basement classroom and support spaces: \$1,300
 - 5.2. Short-Term Costs
 - 5.2.1. Add portable room filtration unit computer lab B07:

4.5.2.1 –Interior Lighting: 1st Floor



E1 – Hallway: Recessed fixtures




E2 – Office: Indirect fixtures




E3 – Center offices: Recessed fixtures (typical)



E4 – Office: Indirect fixtures



E5 – Center offices Hallway: Indirect fixtures



E6 – Community room: Recessed fixtures and natural lighting

4.5.2.2 –Interior Lighting: Basement



E7 – Hallway: Indirect fixtures



E8 – Training room B05: Indirect fixtures



E9 – Office area



E10 – Occupancy detector (typical)



E11 – Rest room fixture (typical)



E12 – AHU Hallway B11: Indirect fixture

4.5.2.3 – Electrical: Service, Distribution, and Receptacles



E13 – 1st Floor breaker panel - 1



E14 – 1st Floor breaker panel - 2



E15 – Basement power and breaker panels



E16 – Electrical conduit

Building Plumbing Systems 4.5.3

1. Fixtures

- 1.1. General Description: The plumbing system is served by a combination of sanitary fixtures, supply and drain piping, and supply water meter service. Serving the men’s and ladies’ rooms, lunch room/kitchen areas, and laundry.
- 1.2. Construction
 - 1.2.1. Five (5) toilets
 - 1.2.2. Six (6) lavatory sinks
 - 1.2.3. One (1) urinal
 - 1.2.4. Two (1) SS kitchen sinks
 - 1.2.5. One (1) janitor’s sink
 - 1.2.6. One (1) wash machine (laundry)
 - 1.2.7. One (1) laundry sink
- 1.3. Condition Assessment
 - 1.3.1. Condition: **NEW**

2. Domestic Water Production

- 2.1 Construction: The domestic water heating system is served by one Bradford-White (1) 50 gallon, commercial water heater and supply piping.

<u>Location</u>	<u>DWH</u>	<u>Type</u>	<u>CAP</u>	<u>Fuel</u>	<u>Pump</u>	<u>SSw</u>	<u>XTank</u>	<u>PRV*</u>	<u>CA</u>	<u>Control</u>	<u>Comments</u>
Basement M.E.R.	1	Tank	50	NG	No	Yes	No	Yes	No	Unit	Installation Date: 1/28/91

Note 1: Water heater safety devices and control testing not included in project scope.
Note 2: Water heater safety devices testing should be performed by competent technician.

CA = Combustion air source: dedicated
 CAP = Storage Capacity: Gallons
 DWH = Domestic Water Heater
 M.E.R. = Mechanical Equipment Room
 NG = Natural Gas
 PRV = Pressure relief valve with extension piping
 SSw = Spill Switch: Draft safety
 XTank = Thermal Expansion Tank

- 2.1.1 Water Heater Condition: **Poor**
- 2.1.2 Supply piping: **Good**

3. Utilities

- 3.1 General Description: Potable water supply
- 3.2 Construction
 - 3.2.1 New meter, shut-off valve, and piping.
 - 3.2.2 No back-flow prevention.**
- 3.3 Condition Assessment: **New**

4. Conclusions:

- 4.1 The plumbing system is a combination of new and existing components. The overall system is in good condition.

5. Estimates: Suggested remedies and Opinion of probable cost

- 5.1 De minimus conditions
 - 5.1.1 Insulate supply pipes from water heaters.
- 5.2 Immediate Costs
 - 5.2.1 Install back-flow preventer: \$2,000.

4.5.2.1 – Plumbing: Fixtures (typical)



P1 – Women's room (typical)



P2 – Men's room



P3 – Water cooling (typical of 2)



P4 – Kitchen sink (typical of 2)

4.5.2.3 – Plumbing: Domestic water



P5 – Domestic Water heater



P6 – Domestic Water heater PRV and piping



P7 – Domestic Water heater control



P8 – Basement Laundry



P9 – Water service: meter and shut-off

Building Fire Protection and Life Safety Systems 4.5.4

1. Fire Extinguishers
 - 1.1. Construction: One (1) fire extinguisher present, one (1) missing.
 - 1.2. Condition Assessment: **Derelict**
 - 1.2.1.1. Physical Deficiencies: One (1) missing unit
 - 1.2.1.2. Maintenance observations: One (1) expired testing date
2. Alarm Systems
 - 2.1. Construction Smoke Alarm: Two (2) observed smoke alarms present, one per floor.
 - 2.2. Condition Assessment Smoke Alarm: **Fair**
 - 2.3. No observable fire pull-stations present. **Potential Code Violation.**

Note: The field audit and PCA did not include functional testing of fire or smoke alarm systems.

3. Smoke Evacuation System and Stairwell Pressurization
 - 3.1. No Smoke Evacuation System or Stairwell Pressurization.
4. Sprinklers and Standpipes
 - 4.1. No sprinkler system present.
5. Emergency Lighting
 - 5.1. Construction: Emergency lighting present at required exists and stairwells.
 - 5.2. Condition Assessment: **New**
6. Ground Fault Interruption
 - 6.1. GFI's not present in all kitchen connections. **Potential Code Violation.**
7. Conclusions:
 - 7.1. The building fire protection and life safety systems are in good condition.
8. Estimates: Suggested remedies and Opinions of probable cost
 - 8.1. De Minimus Conditions
 - 8.1.1. Test fire extinguisher at Community room entrance.
 - 8.2. Short-Term Costs
 - 8.2.1. Add a minimum of four (4) fire extinguishers
 - 8.2.1.1. 1st floor side exit (missing): \$250
 - 8.2.1.2. 1st floor front office hallway: \$250
 - 8.2.1.3. Outside Basement M.E.R.: \$250
 - 8.2.1.4. Basement hallway: \$250
 - 8.2.2. Add a minimum of five(5) smoke-fire detector/alarms:
 - 8.2.2.1. Community room: \$350
 - 8.2.2.2. 1st floor class room: \$350
 - 8.2.2.3. 1st floor front office hallway: \$350
 - 8.2.2.4. 1st floor front center office hallway: \$350
 - 8.2.2.5. Basement hallway: \$350
 - 8.2.3. Add a minimum of one (1) GFI receptacle, first floor kitchen sink: \$300

4.5.4.1 – Fire Protection: Extinguishers, Emergency Lighting, Detectors and Alarms, and Ground Fault Interruption



FP 1 – Extinguisher (testing out-of date)



FP 2 – Basement classroom training area smoke detector B05




LS 1– First Floor emergency existing sign/light (typical)




LS 2– Emergency light (typical)



LS 3 – Basement emergency existing sign/light (typical)



LS 4 – Power receptacle



① Basement Level
1/8" = 1'-0"




The drawings and related digital files are a schematic rendition of the existing conditions of the facility only. Please verify exact field conditions before using these for further construction and renovation work.



Firehouse 14
City of Pittsburgh

Basement Floor Plan		A1.00
Date	07/11/12	Scale 1/8" = 1'-0"
Drawn by	AS	



① L1 Floor Plan
1/8" = 1'-0"



The drawings and related digital files are a schematic rendition of the existing conditions of the facility only. Please verify exact field conditions before using these for further construction and renovation work.




Firehouse 14
City of Pittsburgh

L1 Floor Plan

Date 07/11/13
Drawn by AS

A1.10

Scale 1/8" = 1'-0"



Site Plan
1/32" = 1'-0"

The drawings and related digital files are a schematic rendition of the existing conditions of the facility only. Please verify exact field conditions before using these for further construction and renovation work.



Firehouse 14

City of Pittsburgh

Site Plan		C1.01
Date	07/11/13	
Drawn by	AS	Scale 1/32" = 1'-0"

B110 - FIREHOUSE 14

Tier II: Abbreviated Accessibility Survey					
	Item	Yes	No	N/A	Comments
A. Building History					
1.	Has an ADA survey previously been completed for this property?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
2.	Have any ADA improvements been made to the property?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
3.	Does a Barrier Removal Plan exist for the property?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
4.	Has the Barrier Removal Plan been reviewed/approved by an arms-length third party such as an engineering firm, architectural firm, building department, or other agency, etc.?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
5.	Has building ownership or building management reported receiving any ADA related complaints that have not been resolved?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
6.	Is any litigation pending related to ADA issues?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
B. Parking					
1.	Are there sufficient accessible parking spaces with respect to the total number of reported spaces? (See Table X2.1)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
2.	Are there sufficient van-accessible parking spaces available (96 in. wide by 60 in. aisle)? (See Table X2.1)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
3.	Are accessible spaces marked with the International Symbol of Accessibility? Are there signs reading "Van Accessible" at van spaces?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
4.	Is there at least one accessible route provided within the boundary of the site from public transportation stops, accessible parking spaces, passenger loading zones, if provided, and public streets and sidewalks?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
5.	Do curbs on the accessible route have depressed, ramped curb cuts at drives, paths and drop-offs?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
6.	Does signage exist directing you to accessible parking and an accessible building entrance?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
C. Ramps — N/A					
1.	If there is a ramp from parking to an accessible building entrance, does it meet slope requirements? (1:12 slope or less)?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
2.	Are ramps longer than 6 ft complete with railings on both sides?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
3.	Is the width between railings at least 36 in.?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
4.	Is there a level landing for every 30 ft horizontal length of ramp, at the top and at the bottom of ramps and switchbacks?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
D. Entrances/Exits					
1.	Is the main accessible entrance doorway at least 32 in. wide?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
2.	If the main entrance is inaccessible, are there alternate accessible entrances?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
3.	Can the alternate accessible entrance be used independently?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
4.	Is the door hardware easy to operate (lever/push type hardware, no twisting required, and not higher than 48 in. above floor)?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
5.	Are main entry doors other than revolving doors available?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
6.	If there are two main doors in series, is the minimum space between the doors 48 in. plus the width of any door swinging into the space?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

FIG. X2.1 Abbreviated Accessibility Survey

Tier II: Abbreviated Accessibility Survey					
	Item	Yes	No	N/A	Comments
E. Paths of Travel					
1.	Is the main path of travel free of obstruction and wide enough for a wheelchair (at least 36 in. wide)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
2.	Does a visual scan of the main path of travel reveal any obstacles (phones, fountains, etc.) that protrude more than 4 in. into walkways or corridors?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
3.	Is at least one wheelchair-accessible public telephone available?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
4.	Are wheelchair-accessible facilities (toilet rooms, exits, etc.) identified with signage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
5.	Is there a path of travel that does not require the use of stairs?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
F. Elevators — N/A					
1.	Do the call buttons have visual signals to indicate when a call is registered and answered?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
2.	Is the "UP" button above the "DOWN" button?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
3.	Are there visual and audible signals inside cars indicating floor change?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
4.	Are there standard raised and Braille markings on both jambs of each hoist way entrance?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
5.	Do elevator doors have a reopening device that will stop and reopen a car door if an object or a person obstructs the door?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
6.	Do elevator lobbies have visual and audible indicators of car arrival?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
7.	Are elevator controls low enough to be reached from a wheelchair (48 in. front approach/54 in. side approach)?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
8.	Are elevator control buttons designated by Braille and by raised standard alphabet characters (mounted to the left of the button)?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
9.	If a two-way emergency communication system is provided within the elevator cab, is it usable without voice communication?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
G. Toilet Rooms					
1.	Are common-area public toilet rooms located on an accessible route?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
2.	Are door handles push/pull or lever types?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
3.	Are there audible and visual fire alarm devices in the toilet rooms?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
4.	Are corridor access doors wheelchair-accessible (at least 32 in. wide)?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
5.	Are public toilet rooms large enough to accommodate a wheelchair turnaround (60 in. turning diameter)?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
6.	In unisex toilet rooms, are there safety alarms with pull cords?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
7.	Are toilet stall doors wheelchair-accessible (at least 32 in. wide)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
8.	Are grab bars provided in toilet stalls?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
9.	Are sinks provided with clearance for a wheelchair to roll under (29 in. clearance)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
10.	Are sink handles operable with one hand without grasping, pinching, or twisting?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
11.	Are exposed pipes under sinks sufficiently insulated against contact?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
H. Guestrooms — N/A					
1.	Are there sufficient reported accessible sleeping rooms with respect to the total number of reported guestrooms? (See Table X2.2)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
2.	Are there sufficient reported accessible rooms with roll-in showers with respect to the total number of reported accessible guestrooms? (See Table X2.2)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

FIG. X2.1 Abbreviated Accessibility Survey (continued)

4.3 ASHRAE Level-1 Energy Audit

Executive Summary

The building systems for firehouse 14 have been analyzed and evaluated according to ASHRAE Level-1 methodology and reporting requirements.

The following sections are complimentary to the PCR with additional focus on energy costing, benchmarking, and remediation planning. The detailed information as provided is of an initial nature according to the level-1 structure.

Methodology, calculations, standards, and reference material are drawn from these industry publications:

1. ASHRAE Procedures for Commercial Building Energy Audits -2011 Second Edition
2. ANSI/ASHRAE Standard 105-2007: Standard Methods of Measuring, Expressing, and Comparing Building Energy Performance
3. DOE/EIA US Energy Information Administration: U.S. Commercial Building Energy Intensity -2003 Table 7b.
4. Energy Star Target Finder tool
5. "Commercial Energy Auditing Reference Handbook", Steven Doty, PE, CEM

Scope of Work

The scope-of-work associated with the ASHRAE Level-1 includes the following items.

- Conduct walk-through survey: Completed see - PCR
- Identify low-cost/no-cost recommendations: Completed see - PCR
- Identify capital improvements and potential EEM's: Completed - see PCR
- PEA analysis
- Energy Systems Condition Assessment
- Utility rate structure commodity programs
- EUI target and comparative evaluation
- Potential savings from new EUI target
- Proposed Action Plan: Phase #1

Preliminary Energy Analysis (PEA)

Historical Energy Consumption by Year and Type:

2011 - Electricity

YEAR: 2011

Month	Cooling Degree Days	Billed Demand (kW)	Electric Use (kWh)	Demand Cost (\$)	Total Bill (\$)
January	0	13.2	3920	-	\$361
February	0	10.8	3640	-	\$329
March	0	11.6	3360	-	\$312
April	21	10.4	3240	-	\$297
May	94	14.4	3440	-	\$353
June	182	14.8	5800	-	\$538
July	397	18	6720	-	\$633
August	206	18	7880	-	\$724
September	78	18.4	6600	-	\$626
October	0	15.6	4600	-	\$453
November	0	14	3960	-	\$393
December	0	14	3280	-	\$341
Annual Totals			56,440	\$0	\$5,359

2011 - Natural Gas

YEAR: 2011

Month	Heating Degree Days	MCF	Therms	Total Bill (\$)
January	1240	128.9	1289	\$1,285
February	917	57.7	577	\$577
March	781	56.8	568	\$576
April	350	20.3	203	\$219
May	138	9.5	95	\$112
June	12	6	60	\$83
July	0	6	60	\$83
August	1	7.1	71	\$92
September	87	10	100	\$121
October	401	37	370	\$383
November	532	16.5	165	\$175
December	849	123.3	1233	\$1,161
Annual Totals			4,791	\$4,866

2012 - Electricity

YEAR: 2012

Month	Cooling Degree Days	Billed Demand (kW)	Electric Use (kWh)	Demand Cost (\$)	Total Bill (\$)
January	0	13.2	4000	-	\$391
February	0	10.8	3000	-	\$299
March	4	12.8	3040	-	\$314
April	7	13.2	3080	-	\$320
May	114	13.2	3800	-	\$376
June	181	26.8	7480	-	\$744
July	347	28.4	10280	-	\$985
August	226	32.8	10360	-	\$1,018
September	110	16.4	4840	-	\$484
October	24	8.8	2760	-	\$273
November	0	9.2	3000	-	\$294
December	0	9.2	2960	-	\$291
Annual Totals			58,600	\$0	\$5,789

2012 - Natural Gas

YEAR: 2012

Month	Heating Degree Days	MCF	Therms	Total Bill (\$)
January	993	94.5	945	\$885
February	860	79.7	797	\$758
March	430	41.3	413	\$399
April	456	18.6	186	\$192
May	60	9.3	93	\$107
June	29	3.3	33	\$31
July	0	6	60	\$99
August	1	4.4	44	\$63
September	107	6.4	64	\$71
October	343	16.2	162	\$164
November	719	49.4	494	\$417
December	795	58.9	589	\$494
Annual Totals			3,880	\$3,680

2013 - Electricity

YEAR: 2013

Month	Cooling Degree Days	Billed Demand (kW)	Electric Use (kWh)	Demand Cost (\$)	Total Bill (\$)
January	0	12.4	3200	-	\$330
February	0	11.2	2880	-	\$298
March	0	8.8	2720	-	\$274
April	22	8.4	2960	-	\$290
May	92	12	2920	-	\$305
June	-	16.4	4200	-	392.63
July	-	-	-	-	-
August	-	-	-	-	-
September	-	-	-	-	-
October	-	-	-	-	-
November	-	-	-	-	-
December	-	-	-	-	-
Annual Sub-Totals			18,880	\$0	\$1,891

2013 - Natural Gas

YEAR: 2013

Month	Heating Degree Days	MCF	Therms	Total Bill (\$)
January	988	108.2	1082	\$896
February	998	54.7	547	\$460
March	911	70.8	708	\$591
April	360	37.4	374	\$120
May	151	12.3	123	\$49
June	-	-	-	\$0
July	-	-	-	-
August	-	-	-	-
September	-	-	-	-
October	-	-	-	-
November	-	-	-	-
December	-	-	-	-
Annual Sub-Totals			2,834	\$2,116

Energy Performance Summary

The EUI values include in the performance summary below have been calculated using ASHRAE forms and formulas. Due to the low sampling response for Public order and Safety facilities in the northeast sector, the direct and literal application of these calculations is not advisable. The sections that follow will establish more a realistic target value in the context of a phased energy reduction program. The significant differences in these EUI rating will be treated in terms of potential opportunity.

The total annual cost information data source is the client provided utility bill spread sheet.

ENERGY PERFORMANCE SUMMARY
 Commercial Building Energy Audit Sample Forms

Energy Type	Total Annual Use	Units	Conversion Multiplier	kBtu	Total Annual Cost (\$)
Electricity	58,760	kWh	3.412142	200,497	\$5,711.04
Natural Gas	4,419	Therms	100	441,917	\$4,126.23
Purchased Steam			0	-	
Purchased Hot Water			0	-	
Purchased Chilled Water			0	-	
Oil #:			0	-	
Propane			0	-	
Coal			0	-	
Thermal—On-Site Generated			0	-	
Other			0	-	
Electricity—On-Site Generated			0	-	
Thermal or Electricity—Exported			0	-	
			0	-	
Total				642,414	\$ 9,837.27

Gross Conditioned Area	3635.00
EUI (kBtu/ft ²)	176.73
Target Finder Score*	145
CBECs EUI (for comparable , kBtu/ft ²)	88.3
ECI (\$/ft ²)	\$ 1.87

Notes: The CBECs sampling pool for Public Order and Safety facilities is limited for buildings in the North East sectors and must be interpreted accordingly.

Energy Systems Condition Assessment

The energy systems condition assessment is an additional effort beyond the scope of the ASTM PCA standard and the typical ASHRAE Level-1 requirements. It is a basis for a targeted audit as referred to in ASHRAE standard. This approach supplements the PCR and formal Level-1 to develop a credible EUI target and an actionable remediation program.

This section also provides an initial performance assessment of energy consuming systems and devices as part of the targeted audit effort.

Heating System

Energy System Condition: Boiler system including pump(s), piping, and room radiators - **Derelict**

Boiler System Deficiencies

- Combustion Efficiency: **Poor**
- Age: Near EUL see PCR
- Maintenance Condition: **Poor** see PCR
- Piping System Insulation: **None**

Control System Deficiencies

- Space Set-Point Control: **Poor**. Uncalibrated thermostat, excessive set-point temperatures, and open occupant adjustment
- Boiler Water Set-Point Control: **Poor**. Decommissioned controls, see PCR.
- Set-Back Controls: **None**
- Weekly Scheduling Controls: **None**

Energy Management System Deficiencies

- Active Energy Monitoring and Management System: **None**

Cooling System

Energy System Condition: Room Cooling Units (WACU) - **Derelict**

WACU Deficiencies

- Efficiency: **Poor**
- Age: Near EUL see PCR
- Maintenance Condition: **Poor** see PCR

Control System Deficiencies

- Space Set-Point Control: **Poor**. Uncalibrated integral thermostat, excessive set-point temperatures, and open occupant adjustment
- Set-Back Controls: **None**
- Weekly Scheduling Controls: **None**

Energy Management System Deficiencies

- Active Energy Monitoring and Management System: **None**

Lighting System

Energy System Condition: Interior Lighting - **Poor**

Fixture Deficiencies

- Lamp Efficiency (T12): **Poor**
- Ballast Efficiency: **Poor**
- Age: Near EUL see PCR
- Maintenance Condition: **Poor** see PCR

Control System Deficiencies

- Occupancy Controls: **None**
- Weekly Scheduling Controls: **None**

Energy Management System Deficiencies

- Active Energy Monitoring and Management System: **None**

Potable Water System

Energy System Condition: Water heating and piping - **Derelict**

Heater System Deficiencies

- Combustion Efficiency: **Poor**
- Age: Near EUL see PCR
- Maintenance Condition: **Poor** see PCR
- Piping System Insulation: **None**

Control System Deficiencies

- Set-Back Controls: **None**
- Weekly Scheduling Controls: **None**

Energy Management System Deficiencies

- Active Energy Monitoring and Management System: **None**

Utility rate structure commodity programs

The energy billing and cost data received to date are understood to be directly from local, single source utility companies. Energy rate structures may be reduced through a commodity sourcing approach. Such an approach could include natural gas and electrical energy brokering services. While such services have been successful in reducing cost per kWh and MCF, additional risk of such approach must be carefully considered. It would be expected that energy rate costs could be reduced from 10-15% in a city wide contract. However, such saving would typically require Smart Metering and potential interruption in service, which may not be compatible or acceptable for emergency services facilities. However, full consideration should be given to 'bidding' Natural Gas supply as contractual arrangement may be more acceptable. Further, alternative energy supply opportunities should be explored as peak season interruption obligations are in a state of change, which often favors the consumer.

EUI target and comparative evaluation


The EUI for Firehouse 14 is calculated at 176.73 kBtu/Ft².

The CBECs (Commercial Building Energy Consumption Survey) and 'Target Finder' scores, calculated in the above ASHRAE Energy Performance Summary section, conflict with empirical evidence provided by utility consumption data, Degree-day weather patterns, and the energy systems condition assessment. However, these EUI ratings are useful as bracketing limits.

Basement areas are occasionally occupied, and without extensive terminal heating units, and are not treated formally as conditioned spaces.

An EUI of 130 is proposed as an initial working target pending level-2 modeling or future on-site system sub-metering and data logging efforts.

CBECs EUI	88.30
Target Finder EUI	145.00
Actual EUI	176.73
Proposed EUI	130.00



Potential savings from achieving proposed EUI target

Energy Type	Total Annual Use	Units	Conversion Multiplier	kBtu	Total Annual Cost (\$)
Electricity	43,223	kWh	3.412142	147,483	\$4,200.96
Natural Gas	3,251	therms	100	325,067	\$3,035.19
Purchased Steam			0	-	
Purchased Hot Water			0	-	
Purchased Chilled Water			0	-	
Oil #:			0	-	
Propane			0	-	
Coal			0	-	
Thermal—On-Site Generated			0	-	
Other			0	-	
Electricity—On-Site Generated			0	-	
Thermal or Electricity—Exported			0	-	
				-	
Total				472,550	\$ 7,236.15

Gross Conditioned Area*	3635.00
Actual EUI (kBtu/ft ²)	176.73
Proposed EUI (kBtu/ft ²)	130.00
Proposed ECI (\$/ft ²)	\$ 1.99

*Gross Conditioned Area excludes basement level.

Proposed action plan: Phase #1

Scope: Wireless, WEB based energy management system with wireless instruments including:

- One (1) Boiler Control
- Three (3) Room level heating radiator controls
- Three (3) Lighting controls
- Three (3) Cooling controls
- Set-point, set-back, and scheduling controls
- Insulate basement level hot water supply and return piping
- Insulate basement level domestic water piping
- Re-lamp using T8